



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3914-041
Job Sheet 204924



Part No: D3914-041

Job Qty: 1 pcs

Part Name: Long Basket Lid Assembly (350)



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 12/23/19

Job Tracking No:

Due Date: 1/17/20

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG D4020 REV A SHEET 2, D3914 REV D SHEETS 1,2,3 IPP Rev:A new issue DD 10.03.19 verified by:EC
IPP Rev:B as per dwg revB DD 10.08.18 verified by:EC IPP Rev:C 13.03.14 AS PER DWG REV.pc1 DD
VERF:JLM IPP REV:D 13.06.21 DWG REV.C DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Large Fab - Basket - 1	1 pcs	1/17/20		0.00	10.00	Large Fab - 1		
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		
							Large Fab - 5		
							Large Fab - 6		
							Large Fab - 7		CC
							Large Fab - 8		
							Large Fab - 9		
							Large Fab - 11 (Various)		
							Large Fab - 12		
110	QC 9	1 pcs	1/17/20		0.00	0.00	QC 9 - 10		
							QC 9 - 18	DAS	
							QC 9 - 24	24	
							QC 9 - 43	9-89	
							QC 9 - 50		
							QC 9 - 9		
120	QC 5	1	1/17/20		0.00	0.00	QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19	DAS	
							QC 5 - 22	24	
							QC 5 - 24	9-89	
							QC 5 - 3		
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		



DCS
Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S247865



Part: D3914-041

Job No: 204924

Serial No/Batch: S247865

Revision: A/D

Inspector:

Exp Date:

Instructions: Various STC's

Date: 01/18/20

Plex 12/23/19 10:25 AM Dart.lajeunesse.marie

						QC 5 - 58	
						QC 5 - 68	
						QC 5 - 9	
						QC 5 - 50	
						QC 5 - 30	
						QC 5 - 40	
						QC 5 - 61	
						QC 5 - 81	
130 Powdercoat - 4 Black Sand - B4B	1	pcs	1/17/20	0.00	0.40	Powdercoat - 1 - B4B	
						Powdercoat - 2 - B4B	
						Powdercoat - 3 - B4B	20-01-17
						Powdercoat - 4 - B4B	
135 QC 3	1	pcs	1/17/20	0.00	0.00	QC 3 - 10	
						QC 3 - 13	
						QC 3 - 15	20-01-17
						QC 3 - 17	
						QC 3 - 18	
						QC 3 - 2	
						QC 3 - 28	
						QC 3 - 3	
						QC 3 - 30	
						QC 3 - 34	
						QC 3 - 36	
						QC 3 - 41	
						QC 3 - 51	
						QC 3 - 58	
						QC 3 - 59	
						QC 3 - 68	
						QC 3 - 9	
						QC 3 - 40	
						QC 3 - 19	
						QC 3 - 43	
						QC 3 - 24	
						QC 3 - 61	
						QC 3 - 81	
140 Handfinish - 3-1- WingWalk- B4B	1	pcs	1/17/20	0.00	0.80	Handfinish - 3 - 1 - B4B	20-01-17
						Handfinish - 3 - 2 - B4B	
						Handfinish - 3 - 3 - B4B	
						Handfinish - 3 - 4 - B4B	
						Handfinish - 3 - 5 - B4B	
150 QC 3	1	pcs	1/17/20	0.00	0.00	QC 3 - 10	
						QC 3 - 13	
						QC 3 - 15	
						QC 3 - 17	
						QC 3 - 18	
						QC 3 - 2	
						QC 3 - 28	
						QC 3 - 3	
						QC 3 - 30	
						QC 3 - 34	
						QC 3 - 36	
						QC 3 - 41	
						QC 3 - 51	
						QC 3 - 58	
						QC 3 - 59	20-01-17

DAS 3 9-88

DAS 15 9-89

DAS 59 9-89

160 Packaging 3-1 - Stock - B4B	1 pcs	1/17/20	0.00	0.00	QC 3 - 68	
					QC 3 - 9	
					QC 3 - 40	
					QC 3 - 19	
					QC 3 - 43	
					QC 3 - 24	
					QC 3 - 61	
					QC 3 - 81	
					Packaging 3 - 1 - B4B	ML 20-1-17
					Packaging 3 - 2 - B4B	
					Packaging 3 - 3 - B4B	
					Packaging 3 - 4 - B4B	
					Packaging 3 - 5 - B4B	
					Packaging 3 - 6 - B4B	
					Packaging 3 - 7 - B4B	
					Packaging 3 - 8 - B4B	
					Packaging 3 - 9 - B4B	
					Packaging 3 - 10 - B4B	
					Packaging 3 - 11 - B4B	
					Packaging 3 - 12 - B4B	
					Packaging 3 - 13 - B4B	
					Packaging 3 - 14 - B4B	
					Packaging 3 - 15 - B4B	
					Packaging 3 - 16 - B4B	
					Packaging 3 - 17 - B4B	
					Packaging 3 - 18 - B4B	
					Packaging 3 - 19 - B4B	
					Packaging 3 - 20 - B4B	
					Packaging 3 - 21 - B4B	
					Packaging 3 - 22 - B4B	
					Packaging 3 - 23 - B4B	
					Packaging 3 - 24 - B4B	
					Packaging 3 - 25 - B4B	
					Packaging 3 - 26 - B4B	
					Packaging 3 - 27 - B4B	
					Packaging 3 - 28 - B4B	
					Packaging 3 - 29 - B4B	
					Packaging 3 - 30 - B4B	
					Packaging 3 - 31 - B4B	
					Packaging 3 - 32 - B4B	

Plex 12/23/19 10:25 AM Dart.lajeunesse.marie

				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
				Packaging 3 - 37 - B4B	
170 QC 21 - SA	1	1/17/20	0.00 0.00	QC 21 - SA - 21	DAS
	pcs			QC 21 - SA - 70	21
				QC 21 - SA - 53	8-08

JAN 17 2020

Part Op 100 - (Weld per dwg A/R S.S. rod Batch: 8136920 - 1- assemble ribs , weld as per dwg D3914 using DT9607A 2- weld
 Descriptions: hinge (3) and Mounting brackets as per dwg D3914 ***Visual inspect before welding mesh*** 3- tack weld mesh on
 basket as per dwg D3914 ***Cut out mesh where label plate goes in center off basket lid as per dwg D4020-5. Make sure
 to place mesh correctly on lid, check with label plate before tacking mesh***

110 - QC9- Inspect visual per QSI004- Fusion Welds

120 - QC5- Inspect part completeness to step on W/O

130 - Black Sandtex(Ref:4.3.5.7) per QSI005 4.3 *** mask sides of hinge prior to powdercoat***

135 - QC3- Inspect Part Finish

140 - Wing Walk as per dwg QSI005 4.4 Batch _____ 1- Mask data plate and apply wing walk on outside surface of
 mesh as per dwg 2- Install label as per dwg ***Mask label plate to size of label, use scotchbrite red pad to lightly sand
 area for label, apply label ***

150 - QC3- Inspect Part Finish

160 - Identify as per dwg & Stock Location: _____

170 - QC21- Final Inspection - Work Order Release

Mu# 013863

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581 ✓	Mounting Bracket	2 pcs (2 ea) ✓	100-Large Fab - Basket - 1	S246750 S214321
D3914-1 ✓	Rib	2 pcs (2 ea) ✓	100-Large Fab - Basket - 1	S245728
D3914-7 ✓	Rib	2 pcs (2 ea) ✓	100-Large Fab - Basket - 1	S242129
D4016-3 ✓	Hinge Half, Lid	3 pcs (3 ea) ✓	100-Large Fab - Basket - 1	S221960
D4018-5 ✓	Rib	9 pcs (9 ea) ✓	100-Large Fab - Basket - 1	S2237862
D4020-5 ✓	Mesh (350 Basket Long, Lid)	1 pcs (1 ea) ✓	100-Large Fab - Basket - 1	S229696
D4021-3	Data Plate	1 pcs (1 ea) ✓	100-Large Fab - Basket - 1	S229416
D4035-043	Lid Rib Assembly, Aft (350 Basket)	2 pcs (2 ea) ✓	100-Large Fab - Basket - 1	1X5234497 / 1X246294

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Basket - 1	D2581	2	18	0
	D3914-1	2	8	0
	D3914-7	2	14	0
	D4016-3	3	321	0
	D4018-5	9	99	0
	D4020-5	1	4	0
	D4021-3	1	23	0
	D4035-043	2	5	0

Part Specifications

Specifications could not be found.

Plex 12/23/19 10:25 AM Dart.lajeunesse.marie

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only



Job: _____ Part No. _____		DISPOSITION			DEPARTMENT/PROCESS																																																																																
		Rework Scrap Use-as-is			Skid-tube Machining Large Fab		Cross tube Small Fab Finishing		Eng. (Non-AW) Prod. Eng. Coord. Rec/Store/Packaging		Engineering Water Jet Supplier Quality																																																																										
Date :	Sequence #:	QTY Affected :		MRB (QS1042)																																																																																	
Description Work Order Deviation				Disposition																																																																																	
Root Cause <table border="1"><tr><td>Operator</td><td></td></tr><tr><td>Manufacturing Process</td><td></td></tr><tr><td>Equip/Tooling</td><td></td></tr><tr><td>Handling/Preservation</td><td></td></tr><tr><td>Material</td><td></td></tr><tr><td>Product Improvement</td><td></td></tr><tr><td>Process Improvement</td><td></td></tr><tr><td>Human Factors</td><td></td></tr></table>				Operator		Manufacturing Process		Equip/Tooling		Handling/Preservation		Material		Product Improvement		Process Improvement		Human Factors		FAULT CATEGORY <table border="1"><tr><td>Pressure/Forced</td><td></td><td>Contamination</td><td></td><td>Power Loss/Surge</td><td></td><td>Positioned Wrong</td><td></td></tr><tr><td>Bending</td><td></td><td>Misaligned/off center</td><td></td><td>Folio/Program</td><td></td><td>Outside Tolerance</td><td></td></tr><tr><td>Crushing</td><td></td><td>BOM/Route</td><td></td><td>Grain Direction</td><td></td><td>Drawing</td><td></td></tr><tr><td>Cracks</td><td></td><td>Broken/Damage/Defect</td><td></td><td>Weld</td><td></td><td>Finish</td><td></td></tr><tr><td>Crimp/Kink/Ripple/Wave/Twist</td><td></td><td>Incomplete/Unclear Instructions</td><td></td><td>Wrong Stock Pulled</td><td></td><td>Part Lost/Missing</td><td></td></tr><tr><td>Marks/Chatter</td><td></td><td>Drill Holes</td><td></td><td>Out of Sequence</td><td></td><td>Misread</td><td></td></tr><tr><td>Mislabeled</td><td></td><td>Fit/Function</td><td></td><td>Off-set/Set-up</td><td></td><td></td><td></td></tr></table>										Pressure/Forced		Contamination		Power Loss/Surge		Positioned Wrong		Bending		Misaligned/off center		Folio/Program		Outside Tolerance		Crushing		BOM/Route		Grain Direction		Drawing		Cracks		Broken/Damage/Defect		Weld		Finish		Crimp/Kink/Ripple/Wave/Twist		Incomplete/Unclear Instructions		Wrong Stock Pulled		Part Lost/Missing		Marks/Chatter		Drill Holes		Out of Sequence		Misread		Mislabeled		Fit/Function		Off-set/Set-up			
				Operator																																																																																	
				Manufacturing Process																																																																																	
Equip/Tooling																																																																																					
Handling/Preservation																																																																																					
Material																																																																																					
Product Improvement																																																																																					
Process Improvement																																																																																					
Human Factors																																																																																					
Pressure/Forced		Contamination		Power Loss/Surge		Positioned Wrong																																																																															
Bending		Misaligned/off center		Folio/Program		Outside Tolerance																																																																															
Crushing		BOM/Route		Grain Direction		Drawing																																																																															
Cracks		Broken/Damage/Defect		Weld		Finish																																																																															
Crimp/Kink/Ripple/Wave/Twist		Incomplete/Unclear Instructions		Wrong Stock Pulled		Part Lost/Missing																																																																															
Marks/Chatter		Drill Holes		Out of Sequence		Misread																																																																															
Mislabeled		Fit/Function		Off-set/Set-up																																																																																	
				Completed By																																																																																	
				Lead hand / Supervisor																																																																																	
				QC / QA Coordinator																																																																																	